

Courthouse Square Transfer Documents

26-Oct-10

1	2	3	4	7	8	9	10	11	12	13	14
RecordID	Title	Company	Date	Drawings	Documents	Disciple	Location	Media	Pages	Size	MB
10007	Courthouse Square	Interface Engineering	12/30/98	BD		E	DIR: Abuckle-E	PDF	61	4030	43.9
10008	Courthouse Square	Interface Engineering	12/30/98	BD		M	DIR: Abuckle-M	PDF	41	4030	22.2
10009	Courthouse Square	Arbuckle Costic	01/24/01	RD		A,C,G	DIR:CS_Drawings A1-A2 PDF	PDF	69	4030	166
10010	Courthouse Square	Arbuckle Costic / Century West	01/24/01	RD		A,S	DIR:CS_Drawings A3-S8 PDF	PDF	133	4030	131.6
10011	City of Salem Structural Inspection	City of Salem	01/01/00		INSPECT		DIR:Structural Inspections-555 Court	PDF	208	811	5.84
10012	City of Salem Correspondense	City of Salem	01/01/00				DIR:Correspooondence-555 Court	PDF	6	811	0.43
10013	City of Salem Certificates	City of Salem	01/01/00				DIR:Certificates-555 Court	PDF	2	811	0.95
10014	City of Salem Elect/Mech/Plumbing Inspect	City of Salem	01/01/00				DIR:EMP Inspections-555 Court	PDF	83	811	2.33
10015	City of Salem Final Inspections	City of Salem	01/01/00		INSPECT		DIR:Final Inspections-555 Court	PDF	13	811	0.468
10016	City of Salem Inspections	City of Salem	01/01/00				DIR:Inspections Unspecified-555 Court	PDF	24	811	0.51
10017	City of Salem Permit forms	City of Salem	04/01/99				DIR:Permit Form-555 Court	PDF	2	811	2.4
10018	City of Salem Plans Reviews	City of Salem	04/01/99				DIR:Plans-555 Court	PDF	1654	Varies	291
10019	City of Salem Structural Calcs	City of Salem	04/01/99		CALC		DIR:Structural Calcs and Documents	PDF	1151	811	182
10020	Project Manual	Arbuckle/Costic	01/01/08		SPEC		DIR:CS-Specifications 1998	PDF	1150	811	20.8
10021	Geo Technical Report 1997	Century West Engineering	03/07/97		REPORT	G	DIR:GeoTechnical Report 1997-2008	PDF	64	811	5.8
10022	Geo Technical Report 1998 Addendum #1	Century West Engineering	08/28/98		REPORT	G	DIR:GeoTechnical Report 1997-2008	PDF	11	811	0.8
10023	Environmental Site Assessment- North Block	PSB	08/01/03		REPORT		DIR:GeoTechnical Report 1997-2008	PDF	5	811	0.219
10024	Remediation- Building Survey	Marion County	03/24/10		RFQ		DIR:Building Survey	PDF	50	811	16.1
10026	DEA Quarterly Monitoring 2009	David Evans Associates	06/15/09		REPORT	S	DIR:Engineers DEA	PDF		811	
10027	DEA Structural Evaluation Report 2008 DRAFT	David Evans Associates	01/01/08		REPORT	S	DIR:Engineers DEA	PDF	17	811	0.548
10028	DEA Structural Evaluation Report 2009	David Evans Associates	04/24/09		REPORT	S	DIR:Engineers DEA	PDF	341	811	10.3
10029	DEA Structural Evaluation Report 2004	David Evans Associates	03/18/04		REPORT	S	DIR:Engineers DEA	PDF	4	811	0.212
10030	DEA Structural Evaluation Report 2008	David Evans Associates	01/01/08		REPORT	S	DIR:Engineers DEA	PDF	161	811	8.2
10031	DEA Slab Design Review	David Evans Associates	07/30/07		REPORT	S	DIR:Engineers DEA	PDF	3	811	0.113
10032	Review of Post-Tensioned Concrete Slab System	M.R.Richards Engineering INC	01/01/09		REPORT	S	DIR:Engineers M R Richards Report	PDF	4	811	0.165
10033	Miller Engineering Report 2009	Miller Consulting Engineers, Inc.	10/30/09		REPORT	S	DIR: Miller Engineering Report	PDF	6	811	2.1
10034	Peer Review KGA Letter						DIR: Miller Engineering Report	PDF	16	811	4.6
10036	Estimates for Litigation 2008-2009	sd Deacon	11/28/09		ESTIMATE		DIR: sd DDEACON Esitmate for Litigation	PDF	63	811	14.3
10037	Geotechnical Report 2010	Geo Design	06/14/10		REPORT		DIR:GeoDesign	PDF	130	811	12.2
10038	Geotechnical Field Observation 1999	Century West Engineering	06/01/99		OBSERV		DIR:GeoDesign	PDF	15	811	0.664
10040	Pictures of Damages	Marion County	01/01/07		PIC		DIR:PIC Damage 2007-2008	PDF	54	811	15.6
10041	Pictures of Discovery Phase 2010	Marion County	06/24/10		PIC		DIR:PIC Damage 2007-2008	JPG	114	811	105.3
10042	Pictures Building Settlement	Marion County	03/05/08		PIC		DIR:CS Photos/CS Builiding Settlement 3	JPG	94		100
10043	Pictures Damage in Parking area				PIC		DIR:CS Photos/CS Damage Parking		70		9.7
5,819										1,177	